MR LOWE'S PARTS EMPORIUM































Note: all prices below are +P&P

- 1. 'J' Stainless steel front brake torque arms with four lock tabs. £45.00. Lock tabs only £16.00 Torque arms only £35.00
- 'J' Stainless/bright zinc, brake link- arms. £80.00
- BS40 Carb Cold Start rod actuator link, £15.00
- Fuel tap spacer (allows fuel tap OFF modification on A/B models. £20.00
- Gear position indicator switch £135.00
- GT750 LED gear indicator display. £100.00 (Incorporates under/over charge indication)
- GT380/550 LED gear indicator display. £100.00 (Incorporates under/over charge indication)
- H/dutyS/S clutch actuator arm £35,00
- Solid state (non- diode) combined rectifier/regulator. Direct replacement. £150.00
- Solid state rectifier. Direct replacement £45.00. OEM regulator calibration service £35.00
- Side stand cut-out switch (no wiring mods req) £110.00
- Rear sprocket and Disc brake lock tabs. Bright nickel plated. 3 for £10.00
- New alternator carbon brushes require soldering on fitment. Pair for £7.50
- 14. Water pump re-manufactured and supplied on an exchange basis £175.00 (J/K impeller modification £25 extra)
- Accent Electronic Ignition
 Systems new £150.00. Servicing and repair of systems £30.00.